

## **TELEFAX**

## AMENDMENTS TO THE DRAWINGS

In paragraph 1 of his report, the Examiner objected to the drawings because they fail to show the air interface number 112 (3). For that reason, Applicants submit amended Figure 1, which does not include new material. Amended Figure 1 merely corrects a clerical error. In particular, the interface number 112 (3) and item 112 (3) are described in the Specification, but were missing on original Figure 1. The amended Figure 1 is included herewith on Replacement Sheet.

09/767,362

## Replacement Sheet

1/3




FIG. 1